



REDONDOS



D	E (espesor)
12	1
16	1
20	1
25	1.5
	2
30	1
	1.5
	2
35	1.2
	AUTORROSCADO
	1.5
	2
40	5
	2
	1.3
50	2
	3
	5


REDONDOS



D	E (espesor)
45	1.5
50	1.3
	2
55	5
	1.5
60	1.3
	2.5
70	1.5
	1
80	1.7
	1.65
100	5
	5
120	5

REDONDOS

VARILLAS MACIZAS



VARILLAS MACIZA 12

VARILLAS MACIZA 15

VARILLAS MACIZA 20