



RECTANGULOS

A	B	E (espesor)
20	10	1.2 AUTORROSCADO
20	15	1.5
30	15	1.2 AUTORROSCADO
30	20	2 1.2 2
35	9.9	AUTORROSCADO
40	10	1.3
40	20	1.2 AUTORROSCADO 2 3
40	30	1.5
50	10	1.5
50	20	1.5
50	25	1.3
50	30	1.4 3
60	10	1.1 2
60	20	1.3




RECTANGULOS

A	B	E (espesor)
60	20	2
		2.5
60	30	1.3
		2
60	40	1.3
		2
		3
		4
70	10	1.5
		1.5
70	20	1.3
		1.3
80	20	1.2
		2
80	40	1.3
		2
		3
80	60	1.6
		1.6
100	10	1.5
		1.5
100	20	1.2
		2
100	40	1.4
		1.4



RECTANGULOS

A	B	E(espesor)
100	40	2
		3
100	45	1.4
		2
100	50	1.5
		2
100	60	3
		3
120	20	1.35
		TABIQUE
120	25	1.4
		2
120	40	1.4
		2
120	50	2
		3
120	60	1.35
		2
120	80	2
		2
140	20	1.4
140	60	2
150	20	1.5



RECTANGULOS

A	B	E (espesor)
150	30	1.5
150	40	AUTORROSCADO
150	40	1.4
		1.8
150	50	2
		4
150	80	3
150	100	2
160	40	2
170	50	3
180	50	2
190	20	1.8
200	40	1.8
		2 AUTOR. TABIQUE
200	80	3
		5
250	60	3
300	50	2.5